



DIGGING PROJECT CHECKLIST



Mark Digging Area

Use white paint, flags or stakes to indicate where you plan to dig.



Call 811

Contact 811 at least two working days prior to digging. Provide project details and retain your Underground Service Alert ticket for reference.



Mind the Markings

Allow 48 hours for PG&E to mark underground lines. Keep those markers in place until the project is completed.



Dig Safely

Use hand tools within 24 inches of marked lines. Be alert for hissing, whistling or other signs of gas leaks. If a leak is suspected, evacuate the area, call 911 and notify PG&E.



Backfill & Compact

After project completion, carefully backfill and compact soil as needed.

LEARN MORE AT [SAFETYACTIONCENTER.PGE.COM](https://www.safetyactioncenter.pge.com)